

4. Checking New Version Number.

When the unit has restarted, use a web-browser to check that the firmware version number has been updated. The unit has now been successfully updated.